

AHN Tecan Tips Availability Compatibility Chart

Tecan_Ref.No.	AHN Cat #	Tray	Description	Comment	Fluent Automation Workstation			Freedom EVO/EVOlyzer			
					LIHa		MCA	LIHa		MCA	
					Hanging Tips	SLAS Tips	SLAS	Hanging Tips	SLAS Tips	SLAS	
HANGING TIPS- Conductive tips											
Not Available with Tecan	1-304-F50-7	Grey	standard LIHa conductive tips 10ul	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	1-305-F50-7		standard LIHa conductive tips 10ul with filter	Available from AHN	✓		x	x	✓	x	x
30104803	2-304-B24-7		pure LIHa conductive tips 10ul	Available from AHN	✓		x	x	✓	x	x
30104804	2-305-B24-7		pure LIHa conductive tips 10ul with filter	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	1-314-F50-7	Green	standard LIHa conductive tips 50ul	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	1-315-F50-7		standard LIHa conductive tips 50ul with filter	Available from AHN	✓		x	x	✓	x	x
30032115	1-314-B24-7		pure LIHa conductive tips 50ul	Available from AHN	✓		x	x	✓	x	x
30032114	2-315-B24-7		pure LIHa conductive tips 50ul with filter	Available from AHN	✓		x	x	✓	x	x
10612552	1-329-F50-7	Blue	standard LIHa conductive tips 200ul	Available from AHN	✓		x	x	✓	x	x
10612553	1-330-F50-7		standard LIHa conductive tips 200ul with filter	Available from AHN	✓		x	x	✓	x	x
30000627	1-329-B24-7		pure LIHa conductive tips 200ul	Available from AHN	✓		x	x	✓	x	x
30000629	1-330-B24-7		pure LIHa conductive tips 200ul with filter	Available from AHN	✓		x	x	✓	x	x
10612554	1-404-F50-7	Yellow	standard LIHa conductive tips 1000ul	Available from AHN	✓		x	x	✓	x	x
10612513	1-405-F50-7		standard LIHa conductive tips 1000ul with filter	Available from AHN	✓		x	x	✓	x	x
10612555	1-405-F50-7		standard LIHa conductive tips 1000ul with filter	Available from AHN	✓		x	x	✓	x	x
30000630	1-404-B24-7		pure LIHa conductive tips 1000ul	Available from AHN	✓		x	x	✓	x	x
30000631	1-405-B24-7	Yellow	pure LIHa conductive tips 1000ul with filter	Available from AHN	✓		x	x	✓	x	x
30115239	1-405-B24-7		pure LIHa conductive tips 1000ul wide bore	Not Available		x		x		x	x
HANGING TIPS- Clear tips											
Not Available with Tecan	1-302-F50-0	Grey	standard LIHa clear tips 10ul	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	1-303-F50-0		standard LIHa clear tips 10ul with filter	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	2-302-B24-0		pure LIHa clear tips 10ul	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	2-303-B24-0		pure LIHa clear tips 10ul with filter	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	1-312-F50-0	Green	standard LIHa clear tips 50ul	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	1-313-F50-0		standard LIHa clear tips 50ul with filter	Available from AHN	✓		x	x	✓	x	x
30126096	2-312-B24-0		pure LIHa clear tips 50ul	Available from AHN	✓		x	x	✓	x	x
30126097	2-313-B24-0		pure LIHa Clear tips 50ul with filter	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	1-327-F50-0	Blue	standard LIHa clear tips 200ul	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	1-328-F50-0		standard LIHa clear tips 200ul with filter	Available from AHN	✓		x	x	✓	x	x
30126017	2-327-B24-0		pure LIHa Clear tips 200ul	Available from AHN	✓		x	x	✓	x	x
30126018	2-328-B24-0		pure LIHa Clear tips 200ul with filter	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	1-402-F50-0	Yellow	standard LIHa clear tips 1000ul	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	1-403-F50-0		standard LIHa clear tips 1000ul with filter	Available from AHN	✓		x	x	✓	x	x
Not Available with Tecan	1-403-F50-0		standard LIHa clear tips 1000ul with filter	Available from AHN	✓		x	x	✓	x	x
30126019	2-402-B24-0		pure LIHa Clear tips 1000ul	Available from AHN	✓		x	x	✓	x	x
30126020	2-403-B24-0	pure LIHa Clear tips 1000ul with filter	Available from AHN	✓		x	x	✓	x	x	
ANSI/SLAS TIPS- Conductive											
30104973	1-308-RF40-7	Grey	pure SLAS conductive tips 10ul	Available from AHN	x	✓	x	x	✓	x	x
30104974	1-309-RF40-7		pure SLAS conductive tips 10ul with filter	Available from AHN	x	✓	x	x	✓	x	x
30104975	2-308-R40-7		sterile SLAS conductive tips 10ul	Available from AHN	x	✓	x	x	✓	x	x
30104976	2-309-R40-7		sterile SLAS conductive tips 10ul with filter	Available from AHN	x	✓	x	x	✓	x	x
30057811	1-318-RF40-7	Green	pure SLAS conductive tips 50ul	Available from AHN	x	✓	x	x	✓	x	x
30057813	1-319-RF40-7		pure SLAS conductive tips 50ul with filter	Available from AHN	x	✓	x	x	✓	x	x
30057818	2-318-R40-7		sterile SLAS conductive tips 50ul	Available from AHN	x	✓	x	x	✓	x	x
30057819	2-319-R40-7		sterile SLAS conductive tips 50ul with filter	Available from AHN	x	✓	x	x	✓	x	x
30057814	1-333-RF40-7	Blue	pure SLAS conductive tips 200ul	Available from AHN	x	✓	x	x	✓	x	x
30057815	1-334-RF40-7		pure SLAS conductive tips 200ul with filter	Available from AHN	x	✓	x	x	✓	x	x
30057820	2-333-R40-7		sterile SLAS conductive tips 200ul	Available from AHN	x	✓	x	x	✓	x	x
30057821	2-334-R40-7		sterile SLAS conductive tips 200ul with filter	Available from AHN	x	✓	x	x	✓	x	x
30057816	1-408-RF40-7	Yellow	pure SLAS conductive tips 1000ul	Available from AHN	x	✓	x	x	✓	x	x
30057817	1-409-RF40-7		pure SLAS conductive tips 1000ul with filter	Available from AHN	x	✓	x	x	✓	x	x
30057822	2-408-R40-7		sterile SLAS conductive tips 1000ul	Available from AHN	x	✓	x	x	✓	x	x
30057823	2-409-R40-7		sterile SLAS conductive tips 1000ul with filter	Available from AHN	x	✓	x	x	✓	x	x
30059897			pure SLAS conductive tips 5000ul	Not Available	x		x	x	x	x	x
30065423			pure SLAS conductive tips 5000ul with filter	Not Available	x		x	x	x	x	x
30059898			sterile SLAS conductive tips 5000ul with filter	Not Available	x		x	x	x	x	x
ANSI/SLAS TIPS- Clear tips											
Not Available with Tecan	1-306-RF40-0	Grey	pure SLAS Clear tips 10ul	Available from AHN	x	✓	x	x	✓	x	x
Not Available with Tecan	1-307-RF40-0		pure SLAS Clear tips 10ul with filter	Available from AHN	x	✓	x	x	✓	x	x
Not Available with Tecan	2-306-R40-0		sterile SLAS Clear tips 10ul	Available from AHN	x	✓	x	x	✓	x	x
Not Available with Tecan	2-307-R40-0		sterile SLAS Clear tips 10ul with filter	Available from AHN	x	✓	x	x	✓	x	x
Not Available with Tecan	1-316-RF40-0	Green	pure SLAS Clear tips 50ul	Available from AHN	x	✓	x	x	✓	x	x
Not Available with Tecan	1-317-RF40-0		pure SLAS Clear tips 50ul with filter	Available from AHN	x	✓	x	x	✓	x	x
Not Available with Tecan	2-316-R40-0		sterile SLAS Clear tips 50ul	Available from AHN	x	✓	x	x	✓	x	x
Not Available with Tecan	2-317-R40-0		sterile SLAS Clear tips 50ul with filter	Available from AHN	x	✓	x	x	✓	x	x
Not Available with Tecan	1-331-RF40-0	Blue	pure SLAS Clear tips 200ul	Available from AHN	x	✓	x	x	✓	x	x
Not Available with Tecan	1-332-RF40-0		pure SLAS Clear tips 200ul with filter	Available from AHN	x	✓	x	x	✓	x	x
Not Available with Tecan	2-331-R40-0		sterile SLAS Clear tips 200ul	Available from AHN	x	✓	x	x	✓	x	x
Not Available with Tecan	2-332-R40-0		sterile SLAS Clear tips 200ul with filter	Available from AHN	x	✓	x	x	✓	x	x

	1-405-RF40-0		pure SLAS Clear tips 1000ul	Available from AHN	x	✓	x	x	✓	x
Not Available with Tecan	1-406-RF40-0		pure SLAS Clear tips 1000ul with filter	Available from AHN	x	✓	x	x	✓	x
Not Available with Tecan	2-405-R40-0		sterile SLAS Clear tips 1000ul	Available from AHN	x	✓	x	x	✓	x
Not Available with Tecan	2-406-R40-0	Yellow	sterile SLAS Clear tips 1000ul with filter	Available from AHN	x	✓	x	x	✓	x
MCA and nested tips										
30104977			pure nested conductive tips 10ul	Available from AHN	x	✓	x	x	✓	x
30104978			pure nested conductive tips 10ul with filter	Available from AHN	x	✓	x	x	✓	x
30104979			sterile nested conductive tips 10ul with filter	Available from AHN	x	✓	x	x	✓	x
30083400			pure nested conductive tips 350ul	Not Available	x	x	x	x	x	x
30083401			sterile nested conductive tips 350ul	Not Available	x	x	x	x	x	x
30038608			pure MCA SLAS clear tips 50ul	Not Available	x	x	✓	x	x	✓
30038607			sterile MCA SLAS clear tips 50ul	Not Available	x	x	✓	x	x	✓
30038608			sterile MCA SLAS clear tips 50ul with filter	Not Available	x	x	✓	x	x	✓
30038611			pure MCA SLAS clear tips 100ul	Not Available	x	x	✓	x	x	✓
30038612			sterile MCA SLAS clear tips 100ul	Not Available	x	x	✓	x	x	✓
30038613			sterile MCA SLAS clear tips 100ul with filter	Not Available	x	x	✓	x	x	✓
30038616			pure MCA SLAS clear tips 200ul	Not Available	x	x	✓	x	x	✓
30038617			sterile MCA SLAS clear tips 200ul	Not Available	x	x	✓	x	x	✓
30038618			sterile MCA SLAS clear tips 200ul with filter	Not Available	x	x	✓	x	x	✓
30050348			pure MCA SLAS clear tips 200ul wide bore	Not Available	x	x	✓	x	x	✓
30050349			sterile MCA SLAS clear tips 200ul wide bore	Not Available	x	x	✓	x	x	✓
30046341			pure MCA SLAS clear tips 500ul	Not Available	x	x	✓	x	x	✓
30046342			sterile MCA SLAS clear tips 500ul	Not Available	x	x	✓	x	x	✓
30038610			pure MCA nested for Te-stack clear tips 50ul	Not Available	x	x	✓	x	x	✓
30038609			pure MCA nested for passive stack clear tips 50ul	Not Available	x	x	✓	x	x	✓
30048822			sterile MCA nested for passive stack clear tips 50ul	Not Available	x	x	✓	x	x	✓
30038614			pure MCA nested for passive stack clear tips 100ul	Not Available	x	x	✓	x	x	✓
30048813			sterile MCA nested for passive stack clear tips 100ul	Not Available	x	x	✓	x	x	✓
30038620			pure MCA nested for Te-stack clear tips 200ul	Not Available	x	x	✓	x	x	✓
30038619			pure MCA nested for passive stack clear tips 200ul	Not Available	x	x	✓	x	x	✓
30048824			sterile MCA nested for passive stack clear tips 200ul	Not Available	x	x	✓	x	x	✓
30051802			pure MCA 384 SLAS clear tips 15ul	Not Available	x	x	✓	x	x	✓
30051803			sterile MCA 384 SLAS clear tips 15ul	Not Available	x	x	✓	x	x	✓
30051804			sterile MCA 384 SLAS clear tips 15ul with filter	Not Available	x	x	✓	x	x	✓
30051805			pure MCA 384SLAS clear tips 50ul	Not Available	x	x	✓	x	x	✓
30051806			sterile MCA 384 SLAS clear tips 50ul	Not Available	x	x	✓	x	x	✓
30051807			sterile MCA 384 SLAS clear tips 50ul with filter	Not Available	x	x	✓	x	x	✓
30051808			pure MCA 384SLAS clear tips 125ul	Not Available	x	x	✓	x	x	✓
30051809			sterile MCA 384 SLAS clear tips 125ul	Not Available	x	x	✓	x	x	✓
30051810			sterile MCA 384 SLAS clear tips 125ul with filter	Not Available	x	x	✓	x	x	✓

Key:	✓	Compatible
	x	Non Compatible

Known Machines Compatible with AHN Tecan Type Tips


Workstation	Workstation Model	Hanging Tips	LiHa	SLAS Tips	MCA SLAS	Remarks
Abbot Diagnostics	M2000	✓		x	x	
Adaltis	NexGen Series	✓				
Aurora Biomed	VERSA	✓		✓		Clear Tips Compatible
AusDiagnostics	Ultraplex Alliance system	✓		x	x	
AXA Diagnostics	Everex - SkyLAB 752 -Italy	✓		x	x	
Corbett	CAS-1200	✓		x	x	Uses 200ul and 50ul hanging rack tips conductive
Cybio	Analytik Jena CyBio FELIX	✓		x	x	Clear Tips Compatible
DaAN- China	Gene Automated Nucleic Acid Extraction system	✓		x	x	
Lonza- Swiss	Pyrotec PRO Automated Robotic system	✓		x	x	
Hologic - USA	Panther Fusion	✓		x	x	
Mobidiag Hologic Group - Finland	Amplidiag Easy system	✓		x	x	
Perkin Elmer	Evolution™ P3	✓		✓	x	
	Janus	✓		✓	x	Compatible with Varispan™ Head which is similar to LiHa arm, both clear and conductive
Qiagen	QIAgility	✓		x	x	
Grifols	Procleix Panther system	✓			x	
Youngene Health	Youngene® SP150			✓		
ThermoFisher Scientific	Thermo Fisher Scientific Amplitude Solution	✓				
Sansura Biotech	Sansura Biotech Natch 5	✓		✓		
Mobidiag	Mobidiag Amplidiag® Easy	✓				
Miltenyi Biotec	Miltenyi MultiMACS™ X			✓		Used 1mL and 5mL SLAS conductive tips
NGNY Devices	NGNY AQUA7000	✓				
TelesisBio	BioXp 3200/3250/9600	✓				

Known Robotic Machines that Do not Use Tecan Tips


Workstation	Workstation Model	Hanging Tips	LiHa	SLAS Tips	MCA SLAS	Remarks
-------------	-------------------	--------------	------	-----------	----------	---------

Agilent/Velocity11	Bravo		x	x	x
	VPrep		x	x	x
Beckman Coulter	Biomek 1000		x	x	x
	Biomek 2000		x	x	x
	Biomek 3000		x	x	x
	Biomek 4000		x	x	x
	Biomek i series		x	x	x
	Biomek FX-96/NX-96		x	x	x
	Biomek FX-384/NX-384		x	x	x
	Multimek AP-96		x	x	x
	Multimek AP-384		x	x	x
	Multimek CCS-Head		x	x	x
	Multimek Type II		x	x	x
BioTek	Precision		x	x	x
	Precision XS		x	x	x
Corbett	CAS-4200, CAS-4800		x	x	x
Hamamatsu	6000		x	x	x
	7000		x	x	x
Hamilton	Nimbus		x	x	x
	Microlab STAR		x	x	x
	Microlab STARlet		x	x	x
	Microlab STARplus		x	x	x
Perkin Elmer	Minitrak		x	x	x
	Multiprobe II ET (hanging wafer)		x	x	x
	Multiprobe II HT		x	x	x
	Platetrak		x	x	x
	Zymark RapidPlate		x	x	x
	Sciclone		x	x	x
	Zephyr		x	x	x
ProGroup/Wellpro	3000-96		x	x	x
	3000-384		x	x	x
Qiagen	BioRobot		x	x	x

Similar to Rainin Liquidator uses specially racked LTS tips, these LTS racks are not manufactured by AHN



Hanging Tips



SLAS Rack



Tecan MCA